

FACILITIES SUPPORT SERVICES

Asphalt Playgrounds

Location	Playground Priority	Playground Sq. Footage	Total A/C Replacement	Slurry Seal & Crack Fill (Only)	Engineering Needed	Funding	Notes
John Cabrillo (2019)	1	42065	x		x	Fund 21	Complete removal and replacement, Excessive cracking, Trip hazards
Pony Express (2019)	1	33600	x		x	Fund 21	Complete removal and replacement, Excessive cracking, Tripping hazard, Previous overlay
Bret Harte (2020)	1	36355	x	x	x	Fund 21	(Raised play area) complete removal and replacement, Tripping hazard, (Main play area) repair asphalt, Crack
David Lubin (2020)	1	44585	x		x	Fund 21	Complete removal and replacement of asphalt, Excessive cracking, Tripping hazard, Ponding
Hubert H. Bancroft (2020)	1	50085	x		x	Fund 21	Complete removal and replacement of asphalt, Excessive cracking, Tripping hazard
Sutter (2020)	1	66825	x	x	x	Fund 21	(Southwest play area) complete removal and replacement of asphalt, Excessive cracking, Tripping
Caleb Greenwood (2020)	1	33247	x		x	Fund 21	Complete Removal and replacement, Trip hazards, Excessive cracking, Previous overlay
Warren McClaskey (2020)	2	38910	x		x	Fund 21	Complete removal and replacement of asphalt, Excessive cracking, Tripping hazard
Bear Flag (2021)	2	48828	x		x		Complete removal and replacement of, Excessive cracking (2") , Previous overlay
Alice Birney (2021)	2	35432	x		x		Complete removal and replacement of asphalt, Ponding at hallways, Excessive cracking (2"), Tripping hazard,
American Legion (2021)	2	12925	x		x		Complete removal and replacement, Excessive cracking, Tripping hazard
C.K. McClatchy (2021)	2	59125	x		x		Complete Removal and replacement, Trip hazards, Excessive cracking, Previous overlay
Elder Creek (2021)	2	42900	x		x		Repairs to asphalt areas, Previously overlay and failing. Possible remove and replace
Genevieve F. Didion (2022)	2	50079	x		x		50% of playground needs replacement. Playground replacement during Mod. To be two coat sealed, Stripe
Hollywood Park (2022)	2	39296	x		x		Complete removal and replacement of asphalt, Excessive cracking, Tripping hazard

FACILITIES SUPPORT SERVICES

Asphalt Playgrounds

Location	Playground Priority	Playground Sq. Footage	Total A/C Replacement	Slurry Seal & Crack Fill (Only)	Engineering Needed	Funding	Notes
John D. Sloat (2022)	2	33635	x				Complete removal and replacement of asphalt, Excessive cracking, Tripping hazard
Leonardo da Vinci (2022)	2	44145	x		x		Complete removal and replacement of asphalt, Excessive cracking, Tripping hazard
Mark Twain (2022)	2	110790	x		x		Complete removal and replacement of asphalt, Excessive cracking, Tripping hazard, Previous overlay
PS 7 (2023)	2	28285	x		x		Complete removal and replacement, Excessive cracking, Tripping hazard, Previous overlay
Sam Brannan (2023)	2	67395	x		x		Complete remove and replace, Excessive cracking, no sub-grade under a/c
Theodore Judah (2023)	2	63430	x		x		Complete removal and replacement of asphalt, Excessive cracking, Tripping hazard, Three previous
Washington (2023)	2	21495	x		x		Complete removal and replacement of asphalt, Excessive cracking, Tripping hazard, Previous overlays
Freeport (2023)	2	65186	x		x		Complete removal and replacement of asphalt, Excessive cracking, Tripping hazard, Previous overlays
Will C. Wood (2023)	2	82340	x		x		Complete removal and replacement of asphalt, Excessive cracking, Tripping hazard, Previous overlays
Leataata Floyd (2019)	3	65970		x	x		Repair, Crack fill, Two coat seal, Stripe
Lisbon (2019)	3	47775		x	x		Repair, Crack fill, Two coat seal, Stripe
John Morse (2019)	3	39910		x	x		Room 11 area by ramp A/C needs repair, Crack fill, Seal, Stripe
California (2019)	3	50820		x	x		Repair Damaged areas, Crackfill & Seal Coat
C.P. Huntington (2019)	3	45824		x	x		Crack fill, Two coat seal, Stripe
Clayton B. Wire (2019)	3	57125		x	x		Crack fill, Two coat seal, Stripe

FACILITIES SUPPORT SERVICES

Asphalt Playgrounds

Location	Playground Priority	Playground Sq. Footage	Total A/C Replacement	Slurry Seal & Crack Fill (Only)	Engineering Needed	Funding	Notes
John F. Kennedy (2020)	3	112495		x			Repair, Crack fill, Two coat seal, Stripe
Genesis / Enrollment Center (2020)	3	41046		x	x		Repair, Crack fill, Two coat seal, Stripe
Health Professions (2020)	3	29381		x	x		Repair, Crack fill, Two coat seal, Stripe
James W. Marshall (2020)	3	68371			x		Repair, Crack fill, Two coat seal, Stripe
John H. Still Elem (2020)	3	54920		x	x		Repair, Crack fill, Two coat seal, Stripe
Joseph Bonnheim (2020)	3	69590		x	x		Repair, Crack fill, Two coat seal, Stripe
Kit Carson (2021)	3	41257		x	x		Repair, Crack fill, Two coat seal, Stripe
Maple (2021)	3	36035		x	x		Repair, Crack fill, Two coat seal, Stripe
Mark Hopkins (2021)	3	37640		x	x		Repair, Crack fill, Two coat seal, Stripe
Martin Luther King, Jr.(2021)	3	50330		x	x		Repair, Crack fill, Two coat seal, Stripe
Matsuyama (2021)	3	64915		x	x		Repair, Crack fill, Two coat seal, Stripe
New Technology Charter (2021)	3	17094		x	x		Repair, Crack fill, Two coat seal, Stripe, (West) basketball court scheduled for replacement 2014
Oak Ridge (2022)	3	41770		x	x		Repair, Crack fill, Two coat seal, Stripe
Rosemont (2022)	3	71705		x	x		Repair, Crack fill, Two coat seal, Stripe
Science & Engineering (2022)	3	38655		x	x		Repair, Crack fill, Two coat seal, Stripe

FACILITIES SUPPORT SERVICES

Asphalt Playgrounds

Location	Playground Priority	Playground Sq. Footage	Total A/C Replacement	Slurry Seal & Crack Fill (Only)	Engineering Needed	Funding	Notes
Sequoia (2022)	3	38300		x	x		Repair, Crack fill, Two coat seal, Stripe
Sutterville (2022)	3	61185		x	x		Repair asphalt, Crack fill, Two coat seal, Stripe
Thomas Jefferson (2023)	3	39315		x	x		Repair, Crack fill, Two coat seal, Stripe
West Campus (2023)	3	22025		x	x		Repair, Crack fill, Two coat seal, Stripe
Woodbine (2023)	3	41165		x	x		Tripping hazard from tree roots, crack fill, two coat seal, stripe
George Washington Carver (2023)	4	41534		x	x		Repair, Crack fill, Two coat seal, Stripe
John Bidwell (2023)	4	31924		x	x		Repair, Crack fill, Two coat seal, Stripe
Ethel I. Baker	4	42021				Fund 21	Completed 2013 / Crackfill, Two coat seal & Stripe (Quick Strike)
H.W. Harkness	4	55283				Fund 21	Completed 2013 / Crackfill, Two coat seal & Stripe (Quick Strike)
Pacific	4	57363				Fund 21	Completed 2013 / Crackfill, Two coat seal & Stripe (Quick Strike)
Peter Burnett	4	33470				Fund 21	Completed 2013 / Crackfill, Two coat seal & Stripe (Quick Strike)
William Land	4	31680				Fund 21	Completed 2013 / Crackfill, Two coat seal & Stripe (Quick Strike)
Father Keith B. Kenny	4	44036				Fund 21	Completed 2013 / Crackfill, Two coat seal & Stripe (Quick Strike)
John H. Still Middle	5	101730				EPR	Completed 2014 Total Replacement
Nicholas	5	52336				Fund 21	Completed 2014 Total Replacement

FACILITIES SUPPORT SERVICES

Asphalt Playgrounds

Location	Playground Priority	Playground Sq. Footage	Total A/C Replacement	Slurry Seal & Crack Fill (Only)	Engineering Needed	Funding	Notes
Phoebe A. Hearst	5	39930				Fund 21	Completed 2014 Total Replacement
Sequoia	5	52261				Fund 21	Completed 2014 Total Replacement South Playground
Abraham Lincoln	4	50456				Fund 21	Completed 2015/ Repair, Crackfill & Seal Coat & Stripe (DM)
Albert Einstein	4	99529				Fund 21	Completed 2015/ Repair, Crackfill & Seal Coat & Stripe (DM)
Camellia	4	43457				Fund 21	Completed 2015/ Repair, Crackfill & Seal Coat & Stripe (DM)
Caroline Wenzel	4	50079				Fund 21	Completed 2015/ Repair, Crackfill & Seal Coat & Stripe (DM)
Cesar E. Chavez	4	28822				Fund 21	Completed 2015/ Repair, Crackfill & Seal Coat & Stripe (DM)
Ethel Phillips	4	25947				Fund 21	Completed 2015/ Repair, Crackfill & Seal Coat & Stripe (DM)
Golden Empire	4	56600				Fund 21	Completed 2015/ Repair, Crackfill & Seal Coat & Stripe (DM)
Parkway	4	51755				Fund 21	Completed 2015/ Repair, Crackfill & Seal Coat & Stripe (DM)
Earl Warren	4	82396				Fund 21	Completed 2015/ Repair, Crackfill & Seal Coat & Stripe (DM)
Fern Bacon	5	105629				ERP/21	Completed 2015/ Total Replacement
Isador Cohen	5	58805				Fund 21	Completed 2015/ Total Replacement
Hiram Johnson	5	99982				ERP	Completed 2015/ Total Replacement
Tahoe	5	90115				ERP	Completed 2015/ Total Replacement

FACILITIES SUPPORT SERVICES

Asphalt Playgrounds

Location	Playground Priority	Playground Sq. Footage	Total A/C Replacement	Slurry Seal & Crack Fill (Only)	Engineering Needed	Funding	Notes
Rosa Parks	5	94245				ERP/21	Completed 2015/ Total Replacement
Edward Kemble	4	33300					Presently refinished and striped/ Year unknown
Bowling Green	5	64623				ERP/21	Completed 2016/ Total Replacement
Crocker / Riverside	4	41588				Fund 21	Completed 2016/ Repair, Crackfill & Seal Coat & Stripe
Fruit Ridge	5	99120				ERP	Completed 2016/ Total Replacement
Susan B. Anthony	5	41240				EPR/21	Completed 2016/ Total Replacement
Luther Burbank	5	170100				ERP	Completed 2016/ Total Replacement
A.M. Winn	5	36885				Fund 21	Completed 2018/ Total Replacement
O.W. Erlewine	5	61275				Fund 21	Completed 2018/ Total Replacement
		4,579,802 SQ FT					